

Paulding County Schools - Athletic, PE Facilities Review

Football Stadium		EPHS	HHS	NPHS	PCHS	SPHS
Field Turf	Condition	Turf out of warranty Coloring still good Some signs of wear	Turf out of warranty; Coloring still vibrant; Turf showing least amount of wear compared to other high schools	Turf out of warranty; Signs of wear in multiple locations with visible areas that show shortened pile lengths	Turf out of warranty; Turf colors starting to fade, especially the red areas	Turf out of warranty; Signs of wear in several locations with slight fading of coloring
	Equity	Good	Good	Good	Good	Good
	Functionality	Good; needs electrical added on both home and visitor sidelines	Good; needs electrical added on both home and visitor sidelines	Good; needs electrical added on both home and visitor sidelines	Good; does have electrical installed on home side	Good; needs electrical added on both home and visitor sidelines
	Safety	None	None	None	Areas of turf are slightly elevated at seam lines	None
	Title IX	None	None	None	None	None
	Accessibility	Good	Good	Good	Good	Good
	Other	None	None	None	None	None
	Comments	Serviceability of turf may be extended w/ repairs but will require replacement w/in 5 years	Serviceability of turf may be extended w/ repairs but will require replacement w/in 5 years	Serviceability of turf may be extended w/ repairs but will require replacement w/in 5 years	Serviceability of turf may be extended w/ repairs but will require replacement w/in 5 years	Serviceability of turf may be extended w/ repairs but will require replacement w/in 5 years
	Considerations	Replace turf	Replace turf	Replace turf	Replace turf	Replace turf
Track	Condition	Good	Fair; Track has several areas that have recently starting to separate	Good	Good	Fair; Track has several areas that have recently starting to separate; Track resurfaced at the end of 2017 (warranty ended Dec 2022)
	Equity	8 lane track between home and visitor grandstands	Good; 8 lane	Good; 8 lane	Good: Only 6 lanes	Good; 8 lane
	Functionality	Good	Good	Good		Good
	Safety	Good	Good	Good	None	Good
	Title IX	None	None	None	None	None
	Accessibility	Good	Good	Good	Good	Good
	Other	None	None	Track not located at football stadium, located on Multi-purpose field	None	Track not located at football stadium, located on Multi-purpose field
	Comments	None	None	None	Track cannot be widened due to space limitations	Repair track as needed
	Considerations	None	Repair track	None	None	Repair track
Home Bleachers	Condition	Good; Aluminum bleacher seating	Good; Aluminum bleacher seating on concrete risers; Additional seating (all aluminum) added on both sides of existing bleacher seating area	Good; Aluminum bleacher seating	Poor; Concrete bleachers show signs of wear and degradation	Good; Aluminum bleacher seating
	Equity	Capacity: 2,230	Capacity: 2200	Capacity: 2,470	Capacity: 1475	Capacity: 2,470
	Functionality	Good	Good	Good	Fair	Good
	Safety	None	None	Chain link fencing has been added along handrails on home side grandstands; This creates separation for their specialty/designated seating however, it also creates concerns for egress out of the grandstand area in the event of an emergency	Handrails need to be added and/or repaired at aisles	None
	Title IX	None	None	None	None	None
	Accessibility	Good	Good	Good	Fair	Good
	Other	During turf replacement, front CMU wall constructed along with shotcrete under entire bleacher section to correct and prevent erosion issues	Review water run-off under bleachers	None	None	None

Paulding County Schools - Athletic, PE Facilities Review

Football Stadium		EPHS	HHS	NPHS	PCHS	SPHS
	Comments	None	Needs further investigation	Verify proper egress from bleachers or make appropriate modifications to achieve	Repair bleachers to prevent further degradation; For safety, install/repair handrails	None
	Considerations	None	None	Provide proper egress from bleachers	Repair bleachers and install/repair handrails	None

Paulding County Schools - Athletic, PE Facilities Review

Football Stadium		EPHS	HHS	NPHS	PCHS	SPHS
Visitors bleachers	Condition	Good; Aluminum bleacher seating	Good; Aluminum bleachers	Good; Aluminum bleacher seating	Poor; Concrete bleachers show signs of wear and degradation	Good; Aluminum bleacher seating
	Equity	Capacity: 1,083	Capacity: 1060	Capacity: 1,368	Capacity: 788	Capacity: 1,368
	Functionality	Good	Good	Good	Fair	Good
	Safety	None	None	None	Handrails need to be added at aisles	None
	Title IX	None	None	None	None	None
	Accessibility	Poor; no ADA access into grandstands	Good	Good	Fair	Good
	Other	None	None	None	None	None
	Comments	None	None	None	Repair bleachers to prevent further degradation; For safety, install/repair handrails	None
Stadium Restrooms	Considerations	Provide ADA access to visitor bleachers	None	None	Repair bleachers and install/repair handrails	None
	Condition	Restrooms located on home and visitors sides; Home side restrooms located in concession building; visitor side restrooms located in original fieldhouse building	Restrooms located on home and visitors sides; Home side restrooms are individual buildings and visitor side are located in concession building	Restrooms located on home and visitors sides; Restrooms are located under grandstands in shared building w/ concessions	Restrooms located at both concession stand locations; RR's under home bleacher are in poor condition. RR's in newest concession bldg. are in good condition	Restrooms located on home and visitors sides; Restrooms are located under grandstands in shared building w/ concessions
	Equity	N/A	N/A	N/A	N/A	N/A
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None	None	0	None
	Title IX	None	None	None	None	None
	Accessibility	Good	Good	Good	Good; Visitor's travel distance is further due to location of restrooms	Good
	Other	None	None	None	None	None
Press Box	Comments	None	None	None	None	None
	Considerations	None	None	None	Renovate RR under home bleachers	None
	Condition	Fair	Good with exception of second level staircase; Staircase is wood construction and in disrepair; 2-level press box	Good	Fair; 2-level press box	Good
	Equity	Size: 10x40, 400 sq ft	Size: 20x40, 800 sq ft	Size: 10x40, 400 sq ft	Size: 20x40; 800 sq ft	Size: 10x40, 400 sq ft
	Functionality	Good	Good	Good	Fair	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	N/A	N/A	N/A	N/A	N/A
	Other	None	None	None	None	None
	Comments	None	Replace wood stairs at Press Box	None	None	None
	Considerations	None	Replace stairs at Press Box	None	None	None

Paulding County Schools - Athletic, PE Facilities Review

Football Stadium		EPHS	HHS	NPHS	PCHS	SPHS
Scoreboard	Condition	Good; SPLOST 6 project	Good	Good; SPLOST 6 project	Good	Good
	Equity	Brand: Electromech, 16MM LED display, 'jumbotron'	LED lighting? No Display	Brand: Electromech, 16MM LED display, 'jumbotron'	LED with video display (size of display?, size of board?)	N/A
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	N/A	N/A	N/A	N/A	N/A
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None
Storgae Building	Condition	N/A	N/A	N/A	N/A	N/A
	Equity	N/A	N/A	N/A	N/A	N/A
	Functionality	N/A	N/A	N/A	N/A	N/A
	Safety	N/A	N/A	N/A	N/A	N/A
	Title IX	N/A	N/A	N/A	N/A	N/A
	Accessibility	N/A	N/A	N/A	N/A	N/A
	Other	None	None	None	None	None
	Comments	See Maintenance Section	See Maintenance Section	See Maintenance Section	See Maintenance Section	See Maintenance Section
	Considerations	None	None	None	None	None
Concessions	Condition	Home side: Good; Visitor side: Good	Home side: Good; Visitor side: Good	Home side: Good; Visitor side: Good	Home side: Fair; Visitor side: Good	Home side: Good; Visitor side: Good
	Equity	N/A	N/A	N/A	Home side: 20x40, 800 sq ft Visitor side:?	N/A
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	Good	Good	Good	Good	Good
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None

Paulding County Schools - Athletic, PE Facilities Review

Football Stadium		EPHS	HHS	NPHS	PCHS	SPHS
Ticket Booth	Condition	Ticket booths for both Home and Visitor side, wood construction, structures are residential style storage buildings	Ticket booths for both Home and Visitor side, wood construction, structures are residential style storage buildings	Ticket booths for both Home and Visitor side, CMU construction w/ metal roofing	Poor; Small open air "stick-built" structure	Ticket booths for both Home and Visitor side, CMU construction w/ metal roofing
	Equity	N/A	Size: 8x10, 80 sq ft	Size: 17x17, 289 sq ft	Poor; Small open air "stick-built" structure	Size: 17x17, 289 sq ft
	Functionality	Good, Visitor side has power	Good, units do not have power	Good, buildings have power	Poor; Small open air "stick-built" structure	Good; buildings have power
	Safety	None	None	None	Poor; Small open air "stick-built" structure	None
	Title IX	None	None	None	None	None
	Accessibility	Good	Good	Good	Good	Good
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None
Stadium Lights	Condition	Fair to Poor; Concrete or steel poles w/ metal halide fixtures; Fixtures becoming obsolete	Fair to Poor; Concrete or steel poles w/ metal halide fixtures; Fixtures becoming obsolete	Fair; Concrete or steel poles w/ metal halide fixtures; Fixtures becoming obsolete	Fair to poor; No wooden poles w/ metal halide fixtures; Fixtures becoming obsolete	Fair; Concrete or steel poles w/ metal halide fixtures; Fixtures becoming obsolete
	Equity	N/A	N/A	N/A	N/A	N/A
	Functionality	Fair	Fair	Fair	Fair	Fair
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	N/A	N/A	N/A	N/A	N/A
	Other	None	None	None	None	None
	Comments	Due to obsolescence, replace stadium light fixtures with LED	Due to obsolescence, replace stadium light fixtures with LED	Due to obsolescence, replace stadium light fixtures with LED	Due to obsolescence, replace stadium light fixtures with LED	Due to obsolescence, replace stadium light fixtures with LED
	Considerations	Replace lighting with LED	Replace lighting with LED	Replace lighting with LED	Replace lighting with LED	Replace lighting with LED
Fencing	Condition	Fair to Good, some fencing repairs are needed in various areas	Fair to Good, some fencing repairs are needed in various areas	Fair to Good, some fencing repairs are needed in various areas	Fencing needs repairs, especially in front of home bleachers	Fair to Good, some fencing repairs are needed in various areas
	Equity	Good	Good	Good	Good	Good
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None	None	Fencing placement provides safety/security for field area however, fencing condition could cause personal injury	None
	Title IX	None	None	None	None	None
	Accessibility	N/A	N/A	N/A	N/A	N/A
	Other	0	0	0	None	None
	Comments	Repair existing fencing	Repair existing fencing	Repair existing fencing	Repair existing fencing	Repair existing fencing
	Considerations	Repair existing fencing	Repair existing fencing	Repair existing fencing	Repair existing fencing	Repair existing fencing

Paulding County Schools - Athletic, PE Facilities Review

Football Stadium		EPHS	HHS	NPHS	PCHS	SPHS
Infrastructure	Condition	Good; location has water, electrical, and adequate stormwater drainage	Good; location has water, electrical, and adequate stormwater drainage	Good; location has water, electrical, and adequate stormwater drainage	Good; location has water and electrical and adequate stormwater drainage	Good; location has water, electrical, and adequate stormwater drainage
	Equity	N/A	N/A	N/A	N/A	N/A
	Functionality	N/A	N/A	N/A	N/A	N/A
	Safety	N/A	N/A	N/A	N/A	N/A
	Title IX	N/A	N/A	N/A	N/A	N/A
	Accessibility	N/A	N/A	N/A	N/A	N/A
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None

Paulding County Schools - Athletic, PE Facilities Review

Field House		EPHS	HHS	NPHS	PCHS	SPHS
Home Lockers	Condition	Good	Good	Good	Good	Good
	Equity	Locker count: 110	95 lockers	Locker count: 102	100 lockers	Locker count: 61
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	Good	Good	Good	Good	Good
	Other	None	None	None	None	None
	Comments	Can be managed to accommodate visitors	None	None	None	None
	Considerations	None	None	None	None	None
Visitor Lockers	Condition	None	None	None	None	Good
	Equity	None	None	None	None	Locker count: 61
	Functionality	None	None	None	None	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	None	None	None	None	Good
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None

Paulding County Schools - Athletic, PE Facilities Review

Field House		EPHS	HHS	NPHS	PCHS	SPHS
Offices	Condition	Good	Good	Good	Good	Good
	Equity	Space count: 6 Large office and meeting areas for coaching staff with designated restrooms; Head coaching office w/ separate RR	Space count: 4 Large office and meeting areas for coaching staff with designated restrooms; Head coaching office w/ separate RR	Space count: 1 (head coaches office)	Space count: 4 Head coaches office w/ additional office space	Space count: 2 (head coaches office and coach staff office)
	Functionality	Good	Good	Good	Good	Good
	Safety	Good	Good	Good	None	Good
	Title IX	None	None	None	None	None
	Accessibility	Good	Good	Good	Good	Good
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None
Conference Rms	Condition	Good	Good	Good	Good	Good
	Equity	None	None	Space count: 1 (used as assistant coaches offices too)	None	None
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	Good	Good	Good	Good	Good
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None
Ref Room	Condition	None	None	None according to school; Area being used for girl restroom area	None	Good
	Equity	None	None	None	None	None
	Functionality	None	None	None	None	None
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	None	None	None	None	Good
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None
Girls Restrooms/Showers	Condition	None	None	None	None	Good
	Equity	None	None	None	None	None
	Functionality	None	None	None	None	Good
	Safety	None	None	None	None	None
	Title IX	Not Applicable - space designed and designated for football only	Not Applicable - space designed and designated for football only	Not Applicable - space designed and designated for football only	Not Applicable - space designed and designated for football only	Not Applicable - space designed and designated for football only
	Accessibility	None	None	None	None	Good
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None
Boys Restrooms/Shower	Condition	Good	Good	Good	Good	Good
	Equity	None	None	None	None	None
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None

Paulding County Schools - Athletic, PE Facilities Review

Field House		EPHS	HHS	NPHS	PCHS	SPHS
Boys Restro	Accessibility	Good	Good	Good	Good	Good
	Other	None	Residential plumbing used - causing issues	None	None	None
	Comments	None	Requires further study	None	None	None
	Considerations	None	None	None	None	None

Paulding County Schools - Athletic, PE Facilities Review

Field House		EPHS	HHS	NPHS	PCHS	SPHS
Infrastructure	Condition	Good	Good	Good; space recently renovated to include new Ecore Beast drop rated weightroom flooring, paint, lay-in ceiling, LED lighting, and exterior drainage corrections	Good; School provided 20k upgrade for flooring and paint at local expense	Good; School indicates the carpeting is in poor condition
	Equity	Largest in the District 12,500 SF	10,000 SF	7500 SF	7,500 SF	6840 SF
	Functionality	None	None	None	None	None
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	None	None	None	None	None
	Other	School indicates the concrete floors have started to crack and have chipped paint	Space was previously used for wrestling once football season ended	Space also being used for weight training classroom	None	4 conex units located behind the field house
	Comments	Non-strutural shrinkage cracks observed	None	Overcrowding has led to dual use of the space.	None	Carpet not recommended in locker rooms
	Considerations	None	None	None	None	Replace carpet with proper flooring

Paulding County Schools - Athletic, PE Facilities Review

Baseball Field		EPHS	HHS	NPHS	PCHS	SPHS
Grass	Condition	Good	Fair	Good	Good, erosion and drainage concerns along fence line	Good
	Equity	Infield area behind home plate has artificial turf installed	N/A	N/A	N/A	N/A
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	Good	Good	Good	Good	Good
	Other	Drainage concerns on right field	None	Drainage concerns on right field and behind home plate	None	Drainage concerns across outfield from bullpen area on left field to right field causing water to pool
	Comments	Re-grade outfield to correct drainage issues	None	Re-grade outfield to correct drainage issues	Correct erosion & drainage	Re-grade outfield to correct drainage issues
	Considerations	Correct drainage issues	None	Correct drainage issues	Correct erosion & drainage	Regrade outfield
Lighting	Condition	Fair	Fair	Fair	Fair	Fair
	Equity	Only baseball field that still uses wooden lighting poles	N/A	N/A	N/A	N/A
	Functionality	Poor	Fair	Fair	Fair	Fair
	Safety	None	None	School reports difficulty in seeing balls at dusk/night	None	Possible issues seeing balls at dusk/night
	Title IX	None	None	None	None	None
	Accessibility	N/A	N/A	N/A	Good	N/A
	Other	Below standard lighting levels. PCSD Maintenance provided repairs and adjustments to increase lighting levels on playing field	None	None	None	None
	Comments	Due to condition and functionality, replace light poles and fixtures w/ LED	Due to obsolescence and condition, consider replacing light fixtures with LED	Due to obsolescence, light level, and condition, replace light fixtures with LED	Due to obsolescence and condition, replace light fixtures with LED	Due to obsolescence and condition, replace light fixtures with LED
	Considerations	Replace light poles and fixtures w/ LED	Replace lighting with LED	Replace lighting with LED	Replace lighting with LED	Replace lighting with LED
Dugouts	Condition	Good	Good	Good	Good	Good
	Equity	Size: Home, 1,619sq ft; Visitor, 311 sq ft	Size: Home 10x20, 200sq ft; Visitor 10x20, 200 sq ft	Size: Home 14x40, 560sq ft; Visitor 12x40, 480 sq ft	Size: Home 10x30, 300sq ft, w/locker rm & RR; Visitor?	Size: Home 320 sq ft; Visitor 273 sq ft
	Functionality	Good, Home dugout includes locker room and storage	Good	Good	Good; home dugout contains locker room space; Does space serve Varsity, JV, and Freshman	Good
	Safety	None	Fencing in front of both dugouts is short and does not cover entire dugout entrance	Fencing in front of both dugouts is short and does not cover entire dugout entrance	None	None
	Title IX	None	None	None	None	None
	Accessibility	Good	Good	Good	Good	Good
	Other	Home dugout contains locker room space and storage	Home side dugout has small storage room	Home side has changing area for varsity players; Visitor side has small storage shed located directly behind it	None	Home and Visitor side have same storage area behind dugout. First base side is being utilized as a locker room/changing area
	Comments	District standard home dugout is 300 sf., visitor 300 sf.	For safety, replace dugout fencing	For safety, replace dugout fencing	None	None
	Considerations	None	Replace dugout fencing	Replace dugout fencing	None	None

Paulding County Schools - Athletic, PE Facilities Review

Baseball Field		EPHS	HHS	NPHS	PCHS	SPHS
Fencing	Condition	Fair	Good	Fair to poor	Poor	Good
	Equity	Chain link fence around field: 6'	Chain link fence around field: 6'	Chain link fence around field: 6'	Chain link fence around field, 6' height	Chain link fence around field: 6' height
	Functionality	Good	Good	Good	Good	Good
	Safety	School indicates that the fence is below adequate	None	School reports bottom of fencing is pulling up along the outfield	Fencing leaning due to erosion	None
	Title IX	None	None	None	None	None
	Accessibility	N/A	N/A	N/A	N/A	N/A
	Other	None	None	None	None	None
	Comments	None	None	Repair or replace fencing around field.	Repair fencing once erosion & drainage are addressed	None
	Considerations	Repair or replace fencing	None	Repair or replace fencing	Repair or replace fencing	None
Backstop	Condition	Good	Good	Fair to poor; school indicates it needs to be replaced	Good	Good
	Equity	CMU knee wall w/ ~30' netting	CMU shin wall (shorter than typically knee wall) w/ 30' netting	CMU knee wall w/ 40' netting	CMU knee wall w/ 40' netting	Chain link construction, 20' in height
	Functionality	Fair	Good	Fair	Good	Fair
	Safety	None	None	School indicates the netting needs to be extended to better cover the area	None	None
	Title IX	None	None	None	None	None
	Accessibility	N/A	N/A	N/A	N/A	N/A
	Other	School has a current request to install a new larger backstop net that will provide better foul ball coverage	None	None	None	None
	Comments	SPLOST 6 funding new backstop	None	Repair or replace backstop netting	None	None
	Considerations	None	None	Repair or replace backstop netting	None	None
Irrigation	Condition	Good	Good	Good	Good	Good
	Equity	Has operable irrigation	Has operable irrigation	Has operable irrigation	Has operable irrigation	Has operable irrigation
	Functionality	Good	Indications that pressure not adequate	Indications that coverage not adequate	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	N/A	N/A	N/A	N/A	N/A
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None

Paulding County Schools - Athletic, PE Facilities Review

Baseball Field		EPHS	HHS	NPHS	PCHS	SPHS
Bleachers	Condition	Good	Good	Good	Good	Good
	Equity	Upgraded Aluminum seating home side, portable aluminum seating on visitors side; Size: Home 10-tier	Mobile aluminum seating. Size: Home 5-tier	Aluminum seating. Size: 10-tier behind backstop; Home side, 5-tier; Visitor side, 5-tier	N/A	Aluminum portable seating.
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None	None	No hand railing	None
	Title IX	None	None	None	None	Shared with softball
	Accessibility	Good	Good	Good	Good	Good
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None
Boys RR	Condition	Good	Good	Good	Fair	Good
	Equity	Number of fixtures: 3; Baseball utilizes the restroom facilities at the football visitors concession building	Baseball utilizes the restroom facilities at the football visitors concession building	Fixture count: 3	Single stall	Fixture count: 3
	Functionality	Good	School indicates the distance is too far and since these restrooms are for "football", they do not have designated restrooms for baseball	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	Good	Good	Good	Poor, not ADA compliant (confirm?)	Good
	Other	None	None	None	None	None
	Comments	None	Travel distance to stadium RR approx. 400 ft.	None	Confirm that restrooms are ADA compliant	None
	Considerations	None		None	None	None
Girls RR	Condition	Good	Good	Good	Fair	Good
	Equity	Number of fixtures: 3; Baseball utilizes the restroom facilities at the football visitors concession building	Baseball utilizes the restroom facilities at the football visitors concession building	Fixture count: 3	Single stall	Fixture count: 3
	Functionality	Good	School indicates the distance is too far and since these restrooms are for "football", they do not have designated restrooms for baseball	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	Good	Good	Good	Poor, not ADA compliant (confirm?)	Good
	Other	None	None	None		None
	Comments	None	Travel distance to stadium RR approx. 400 ft.	None	Confirm that restrooms are ADA compliant	None
	Considerations	None	None	None	None	None

Paulding County Schools - Athletic, PE Facilities Review

Baseball Field		EPHS	HHS	NPHS	PCHS	SPHS
Bulpen	Condition	Good; artificial turf construction	Good; dirt construction	Good; Home side, turf construction; Visitor side, grass construction	Good; dirt construction	Good; grass and dirt construction
	Equity	N/A	N/A	N/A	N/A	N/A
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	N/A	N/A	N/A	N/A	N/A
	Other	None	None	None	None	School indicates a drainage concern due to "negative" drop coming from adjacent areas causing water to pool in this area
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	Correct drainage issue in Bull Pen
Scoreboard	Condition	Good	Good	Good	Good (SPLOST 6 purchase)	Good; SPLOST 6 project
	Equity	LED	N/A	not LED	N/A	N/A
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	N/A	N/A	N/A	N/A	N/A
	Other	Purchased by former student and current MLB player	None	Part of scoreboard not working.	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	Repair scoreboard	None	None
Concession	Condition	Good	Fair to poor; wood construction with several issues visual noted	Good	Fair	Good
	Equity	only concession area that has approved and functional hood system allowing them to cook inside	N/A	N/A	N/A	N/A
	Functionality	Good	Good	Good		Good
	Safety	None	Code violations and poor construction practices	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	Good	Good	Good	Fair	Good
	Other	None	None	None	None	None
	Comments	None	Poor condition, poor construction.	None	None	None
	Considerations	None	Replace Concession	None	None	None

Paulding County Schools - Athletic, PE Facilities Review

Baseball Field		EPHS	HHS	NPHS	PCHS	SPHS
Press Box	Condition	Good; wood construction	Fair to poor; wood construction with several issues visual noted	Good	Good	Good
	Equity	N/A	N/A	N/A	N/A	N/A
	Functionality	Good	Good	Good	Good	Good
	Safety	None	Code violations and poor construction practices	Staircase, wood construction in poor condition due to wear and roof drainage concerns (no gutters)	None	Staircase, wood construction in fair condition
	Title IX	None	None	None	None	
	Accessibility	Not applicable	Not applicable	Not applicable	Not applicable	Not applicable
	Other	None	None	None	None	None
	Comments	Press Box built before 2010 ADA standard addressed Press Boxes	Extensive deficiencies need to be addressed	For safety, replace press box staircase and install gutters. Press Box built before 2010 ADA standard addressed Press Boxes	Press Box built before 2010 ADA standard addressed Press Boxes	Replace wood stairs. Press Box built before 2010 ADA standard addressed Press Boxes
	Considerations	None	Renovate Press Box	Replace stairs at Press Box, install gutters	None	Replace stairs at Press Box
Hitting Facility	Condition	Good	Fair to poor	Good	Good	Good
	Equity	Size: 70x100, 7,068 sq ft; Enclosed steel building w/ power for outlets and lights, no HVAC	Size: 30x60, 1,800 sq ft; Open pavilion wood construction	Size: 30x70, 2,100 sq ft; Enclosed metal building with 30 amp power service w/ LED lighting: no HVAC conditioning but does have adequate power to run upright fans for ventilation	Size: 40x80, 3200sq ft.	40x80 open air concrete slab. Does not allow any protection from elements during practices, especially wet weather.
	Functionality	Good	Fair	Good	Good	Poor
	Safety	None	Electrical had to be disconnected due to safety concerns and code noncompliance	None	None	None
	Title IX	None	None	Shared w/ softball	None (shared with softball)	Shared w/ softball
	Accessibility	Good	Good	Good	Fair	Good
	Other	None	None	None	None	None
	Comments	None	Replacement Hitting Facility is planned	None	None	Replacement Hitting Facility is planned
	Considerations	None	None	None	None	None
Infrastructure	Condition	Good. Location has water, electrical, and stormwater drainage	Good. Location has water, electrical, and stormwater drainage	Good. Location has water, electrical, and stormwater drainage	Good. Location has water, electrical, and stormwater drainage. Concerns of erosion on outside field fence line	Good. Location has water, electrical, and stormwater drainage
	Equity	N/A	N/A	N/A	N/A	N/A
	Functionality	None	None	None	None	None
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	None	None	None	None	None
	Other	None	None	None	None	Drainage concerns across multiple locations have been noted by the school
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None

Paulding County Schools - Athletic, PE Facilities Review

Softball Field		EPHS	HHS	NPHS	PCHS	SPHS
Grass	Condition	Good	Fair; drainage issues	Good	Good	Good
	Equity	N/A	N/A	N/A	N/A	N/A
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	Good	Good	Good	Good	Good
	Other	None	None	None	None	Drainage concerns across outfield from bullpen area on left field to right field causing water to pool in various locations
	Comments	None	Address drainage issues on softball field and dugouts	None	None	Re-grade outfield to correct drainage issues
	Considerations	None	Correct drainage on field	None		Re-grade outfield to correct drainage issues
Lighting	Condition	Good	Good	Good	Good	Good
	Equity	N/A	N/A	N/A	N/A	N/A
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	N/A	N/A	N/A	N/A	N/A
	Other	None	None	School indicates that additional lighting could be added near bullpen area	None	None
	Comments	Lighting to be phased out, replace w/ LED	Due to obsolescence, consider replacing light fixtures with LED	None	Due to obsolescence and condition, replace light fixtures with LED	Due to obsolescence and condition, replace light fixtures with LED
	Considerations	Replace light poles and fixtures w/ LED	Replace lighting with LED	Replace lighting with LED	Replace lighting with LED	Replace lighting with LED
Dugouts	Condition	Good; Visitor dugout constructed as a SPLOST 6 project	Fair; drainage concerns exist that fill the dugout area with infield sand mix	Good	Good	Good
	Equity	Size: Home 1,619 sq ft; Visitor 175 sq ft	Size: Home 10x30, 300 sq ft; Visitor 10x30, 300 sq ft	Size: Home side 12x30, 360 sq ft; Visitor 12x30, 360 sq ft	Size: Home 10x30, 300sq ft. Home dugout has locker room	Size: ~450 sq ft; Visitor ~450 sq ft
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	No RR in softball locker room compared to baseball	None
	Accessibility	Good	Good	Good	Good	Good
	Other	Home side dugout building also includes restroom, storage, locker room, and hitting facility	None	Home side (1st baseline) has storage or locker room area located behind it	None	None
	Comments	District standard home dugout is 300 sf., visitor 300 sf.	Address drainage issues on softball field and dugouts	None	RR at Press Box is being utilized	None
	Considerations	None	Correct drainage at dugouts	None	None	None

Paulding County Schools - Athletic, PE Facilities Review

Softball Field		EPHS	HHS	NPHS	PCHS	SPHS
Fencing	Condition	Good	Good	Good	Poor (confirm?)	Good
	Equity	Chain link fence around field, 5'	Chain link fence around field, 5'	Chain link fence around field, 5'	Chain link fence around field, 5'	Chain link fence around field, 5' height
	Functionality	Good	Good	Good	Good	Good
	Safety	School indicates additional fencing around spectator areas	None	Fencing in front of both dugouts is short and does not cover entire dugout entrance	None	None
	Title IX	None	None	None	None	None
	Accessibility	N/A	N/A	N/A	N/A	N/A
	Other	None	None	None	None	None
	Comments	None	None	None	If fencing is poor, replace	None
	Considerations	None	None	Replace fencing at dugouts	Replace fencing	None
Backstop	Condition	Good	Good	Good	Good	Good
	Equity	CMU knee wall w/ ~30' netting. This was constructed as a SPLOST 6 project	Tubular steel support w/ netting 20' in height	CMU knee wall w/ 40' netting	Chain link construction, 40' (?) (more like 20')	Chain link fencing, ~12'-15' in height
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None	School indicates the netting needs to be extended to better cover the area	None	None
	Title IX	None	None	None	None	None
	Accessibility	N/A	N/A	N/A	N/A	N/A
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	Repair or replace backstop netting	None	None
Irrigation	Condition	Good	Poor; constant breaks have created multiple sinkholes and have resulted in multiple repairs since original installation on and off the field area	Good	Good	Good
	Equity	Has operable irrigation	Has operable irrigation	Has operable irrigation	Has operable irrigation	Has operable irrigation
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None, except when a break creates sinkhole area	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	N/A	N/A	N/A	N/A	N/A
	Other	None	None	None	None	None
	Comments	None	Due to poor condition, replace Irrigation system	None	None	None
	Considerations	None	Replace irrigation system	None	None	None

Paulding County Schools - Athletic, PE Facilities Review

Softball Field		EPHS	HHS	NPHS	PCHS	SPHS
Bleachers	Condition	Good	N/A	N/A	Good	Good
	Equity	N/A	N/A	N/A	N/A	Aluminum portable seating
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None	None	No hand railing	None
	Title IX	None	None	None	None	Shared with softball
	Accessibility	Good	Good	Good	Good	Good
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None
Boys RR	Condition	Good	Good	Good	Fair	Good
	Equity	Press box houses 2 unisex restrooms	N/A	Fixture count: 3	Single stall	Fixture count: 3
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	Good	Good	Good	Not ADA compliant by current standards	Good
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	Renovate and modify RR to meet ADA	None
Girls RR	Condition	Good	Good	Good	Fair	Good
	Equity	Press box houses 2 unisex restrooms		Fixture count: 3	Single stall	Fixture count: 3
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	Good	Good	Good	Not ADA compliant by current standards	Good
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	Renovate and modify RR to meet ADA	None

Paulding County Schools - Athletic, PE Facilities Review

Softball Field		EPHS	HHS	NPHS	PCHS	SPHS
Bullpen	Condition	None	Good; dirt and grass construction	Good; dirt and grass construction	Good; dirt construction	Good; grass and dirt construction
	Equity	None	None	None	None	None
	Functionality	None	Good	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	None	Good	Good	Good	N/A
	Other	None	None	None	None	School indicates drainage concern due to "negative" drop coming from adjacent areas causing water to pool
	Comments	None	None	None	None	None
	Considerations	Provide Bull Pen	None	None	None	Correct drainage issue in Bull Pen
Scoreboard	Condition	Good	Good	Good	Good (SPLOST 6 purchase)	Good; SPLOST 6 project
	Equity	None	None	not LED	None	None
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	N/A	N/A	N/A	N/A	N/A
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None
Concession	Condition	Good	Good	Good	Fair	Good
	Equity	None	None	None	None	None
	Functionality	Good	Good	Good	None	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	Good	Good	Good	Fair	Good
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	Renovate Concessions	None

Paulding County Schools - Athletic, PE Facilities Review

Softball Field		EPHS	HHS	NPHS	PCHS	SPHS
Press Box	Condition	Good	Good	Good; Same press box building used for baseball	Fair, Wooden construction starting to show signs of wear and degradation	Good
	Equity	None	None	None	None	None
	Functionality	Good	Fair to poor; limited to no visibility to first base	Good	Good	Good
	Safety	Staircase, wood construction in fair condition	None	Staircase, wood construction in poor condition due to wear and roof drainage concerns (no gutters)	None	Staircase, wood construction in fair condition
	Title IX	None	None	None	None	
	Accessibility	Not applicable.	Not applicable.	Not applicable.	Not applicable.	Not applicable.
	Other	None	None	None	None	Shared w/ softball
	Comments	Due to condition, replace stairs to Press Box; Press Box built before 2010 ADA standard addressed Press Boxes	Press Box built before 2010 ADA standard addressed Press Boxes	See comment on Baseball Field	None	Repair or replace wood stairs; Press Box built before 2010 ADA standard addressed Press Boxes
	Considerations	Replace stairs to Press Box	None	Replace stairs to Press Box	Renovate Press Box	Replace stairs to Press Box.
Hitting Facility	Condition	Good	None	Good	Good	Good
	Equity	Softball has their own designated indoor hitting facility	No hitting Facility	Size: 30x70, 2,100 sq ft; Enclosed metal building with 30 amp power service w/ LED lighting: no HVAC conditioning but does have adequate power to run upright fans for ventilation	Size: 40x80, 1200sq ft, electrical	40x80 open air concrete slab; Does not allow any protection from elements during practices, especially wet weather
	Functionality	Good	None	Good	Good	Poor
	Safety	None	None	None	None	None
	Title IX	None	None	Shared w/ softball	None (shared with baseball)	Shared w/ softball
	Accessibility	Good	None	Good	Fair	Good
	Other	None	None	None	None	None
	Comments	None	Hitting Facility plans under review	None	None	Replacement Hitting Facility is planned
	Considerations	None	None	None	None	None
Infrastructure	Condition	Good. Location has water, electrical, and stormwater drainage	Over all condition is fair however, with irrigation and drainage concerns, poor conditions do exist that limit the functionality of the entire space	Good. Location has water, electrical, and stormwater drainage	Fair, drainage issue at press box building along poured concrete wall and stair access area	Good. Location has water, electrical, and stormwater drainage
	Equity	None	None	None	None	None
	Functionality	None	None	None	None	None
	Safety	School would like the addition of security cameras; There have been several vandalism events and break-ins over the years in this area	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	None	None	None	No direct ADA accessibility to softball field area	None
	Other	None	None	None	None	Drainage concerns across multiple locations have been noted by the school
	Comments	None	None	None	Access provided via golf cart	None
	Considerations	None	None	None	None	None

Paulding County Schools - Athletic, PE Facilities Review

Multi-Purpose Field		EPHS	HHS	NPHS	PCHS	SPHS
Grass	Condition	Fair to poor, sod construction; Per the school: These fields are used by band, football, soccer, lacrosse, and Track & Field; Condition is inadequate (needs leveling, fertilization, irrigation, and pre-emergent)	Fair, sod construction	Good; sod construction	Fair on front half, poor on rear half	Good; sod construction
	Equity	School has 3 practice fields, 1 at HS and 2 at EPMS	School has 2 practice fields	School has 1 practice field, but also uses McClure Middle's PE/Athletic field	None	School has 1 practice field
	Functionality	Good	None	Good	None	Good
	Safety	None	None	Students walk to the practice field requiring them to cross active traffic lanes	None	None
	Title IX	None	None	None	None	None
	Accessibility	Good		Fair; PE/Athletic field at McClure does not have the best accessible route	None	Good
	Other	None	None	None	None	None
	Comments	Due to extensive use and poor condition, recommend renovating field	None	Provide crosswalk and signage	Renovate field due to poor condition	None
	Considerations	Renovate field	None	Provide crosswalk and signage	Renovate field	None
Lighting	Condition	None	None	Good	None	Good
	Equity	None	None	Both fields having lighting	None	None
	Functionality	None	None	Good; however, they do use portable lighting units to use in conjunction with existing lighting at McClure field	None	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	None	None	N/A	None	N/A
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None
Fencing	Condition	None	None	Good	None	Good; fence only on one side separating field from drive to field house
	Equity	None	None	School field has limited perimeter fencing, McClure field has none	None	None
	Functionality	None	None	None	None	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	None	None	None	None	Good
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None

Paulding County Schools - Athletic, PE Facilities Review

Multi-Purpose Field		EPHS	HHS	NPHS	PCHS	SPHS
Irrigation	Condition	Does have irrigation, but condition is unknown	Does have irrigation, but condition is unknown	Does have irrigation, but condition is unknown	Does have irrigation, but condition is unknown	Does have irrigation, but condition is unknown
	Equity	None	None	None	None	None
	Functionality	None	None	None	None	None
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	None	None	None	None	None
	Other	None	None	None	None	None
	Comments	Verify irrigation operation or repair before renovation of field	None	None	Verify irrigation operation or repair before renovation of field	None
	Considerations	None	None	None	None	None
Bleachers	Condition	None	None	Good	None	None
	Equity	None	None	Aluminum portable bleachers at school field, McClure has none	None	None
	Functionality	None	None	Good	None	None
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	None	None	Good	None	None
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None
Boys Restroom	Condition	None	None	None	None	None
	Equity	None	None	None	None	None
	Functionality	None	None	None	None	None
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	None	None	None	None	None
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None

Paulding County Schools - Athletic, PE Facilities Review

Multi-Purpose Field		EPHS	HHS	NPHS	PCHS	SPHS
Girls Restroom	Condition	None	None	None	None	None
	Equity	None	None	None	None	None
	Functionality	None	None	None	None	None
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	None	None	None	None	None
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None
Scoreboard	Condition	None	None	None	None	None
	Equity	None	None	None	None	None
	Functionality	None	None	None	None	None
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	None	None	None	None	None
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None
Infrastructure	Condition	None	None	School field also serves track and field and has their 8 lane track surrounding it; McClure field has been upgraded and modified over the years to accommodate the Athletic program needs of the High School; The original field has both football area and baseball/softball field; The baseball/softball field have been removed	None	Practice field hosts track and field events; There is no spectator seating and due to the space limitations between the field house access drive and the practice field, no seating can be placed in this area
	Equity	None	None	None	None	None
	Functionality	None	None	None	None	None
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	None	None	None	None	None
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None

Paulding County Schools - Athletic, PE Facilities Review

Tennis Courts		EPHS	HHS	NPHS	PCHS	SPHS
Courts	Condition	Good	Fair	Poor; courts need to be resurfaced	Good	Good
	Equity	4 courts	4 courts	4 courts	4 courts	4 courts
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	Good	Good	Good	Good	Good
	Other	School indicates they need windscreens	None	Courts were scheduled for resurfacing however, this was postponed due to the Addition being constructed on site	None	None
	Comments	None	None	Re-surface courts	None	None
	Considerations	None	None	Re-surface courts	None	None
Nets	Condition	Good	Fair	Fair	Good	Good
	Equity	None	None	None	None	None
	Functionality	Good	Good	Good	None	Good
	Safety	None	Some anchor strapping is in need of repair	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	N/A	N/A	N/A	None	N/A
	Other	None	None	School indicates they may need to be replaced soon	None	School indicates they may need to be replaced soon
	Comments	None	None	Replace netting	None	None
	Considerations	None	Repair netting	Replace netting	None	Replace netting
Fencing	Condition	Good	Good	Good	Good	Good
	Equity	Courts covered on all four sides;	Courts covered on all four sides; 10' height	Courts covered on all four sides; 12' height	Courts covered on all four sides	Courts covered on all four sides; 12' height
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	N/A	N/A	N/A	None	N/A
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None

Paulding County Schools - Athletic, PE Facilities Review

Tennis Courts		EPHS	HHS	NPHS	PCHS	SPHS
Lighting	Condition	Good	Good	Good	Good	Good
	Equity	Metal halide fixtures	Metal halide fixtures	Metal halide fixtures	Metal Halide fixtures	Metal halide fixtures
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	N/A	N/A	N/A	N/A	N/A
	Other	None	None	None	None	None
	Comments	Lighting to be phased out, replace w/ LED	Due to obsolescence, replace light fixtures with LED	Due to obsolescence, replace light fixtures with LED	Due to obsolescence, replace light fixtures with LED	Lighting to be phased out, replace w/ LED
Considerations		Replace light poles and fixtures w/ LED	Replace lighting with LED	Replace light fixtures with LED	Replace lighting with LED	Replace light fixtures w/ LED
Bleachers	Condition	Good	Good	None	Good	Good
	Equity	Aluminum portable bleachers	Aluminum; portable units moved back and forth from softball each year	None	Portable	Aluminum portable bleacher units
	Functionality	Good	Good	None	Good	Fair
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	Fair, no true ADA accessible route	Good (no designated ADA spectator area?)	None	No designated ADA spectator area	Poor, no ADA access to bleacher/spectator area
	Other	None	None	None	None	None
	Comments	Provide accessible route to bleachers. Consider small concrete pad for ADA seating area	Consider small concrete pad for ADA seating area	None	Is there ADA route to tennis courts? Consider small concrete pad for ADA seating area	Consider small concrete pad for ADA seating area
Considerations		Provide accessible route to bleachers. Provide ADA spectator area	Provide ADA spectator area	Provide portable bleachers	Provide ADA spectator area	Provide ADA spectator area
Infrastructure	Condition	None	None	None	None	None
	Equity	None	None	None	None	None
	Functionality	None	None	None	None	None
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	None	None	None	None	None
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
Considerations		None	None	None	None	None

Paulding County Schools - Athletic, PE Facilities Review

Weight Room		EPHS	HHS	NPHS	PCHS	SPHS
Room Size	Condition	Good	Good	Fair	Good	Good
	Equity	Size: 8,034 sq ft.	Size: 4,115 sq ft	Inside main school building: 1,795+1,953=3,748 sq ft; Field house, ~2,556 sq ft. Total: 6,304 SF	building: 4,560 sq ft	Size: 1,971 Sq ft
	Functionality	Good	Good	Fair, space is limited to house all the classes they have scheduled. Current renovation will increase	None	Good
	Safety	None	Using auxiliary gym as dressing room (aux gym has exterior doors with windows plus they have an active security camera)	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	Good	Good	Good	Good	Good
	Other	Facility built by Booster Club	No designated restrooms or dressing area	Overcrowding and course offerings require two weight rooms	None	None
	Comments	None	Provide alternative management solution for dressing room	Requires further study	None	None
	Considerations	None	None	None	None	None
Location	Condition	None	None	Inside main building: Good, Field house: Poor	None	Good
	Equity	Bottom floor of field house building	located in auxiliary and JROTC building	School utilizes 2, 1 inside main building and 1 in field house building	None	Inside main building next to auxiliary gym
	Functionality	None	None	None	None	None
	Safety	None	None	Student must cross an active traffic lane to get to Field house building	None	None
	Title IX	None	None	None	None	None
	Accessibility	None	None	None	None	Good
	Other	None	None	None	None	None
	Comments	None	None	Provide designated/marked crosswalk	None	None
	Considerations	None	None	Provide crosswalk and signage	None	None
Flooring	Condition	Fair to poor	Good	Inside main building: Fair, Field house: Good	Fair	Good
	Equity	Rubber flooring; Unknown if drop rated	Ecore sports flooring w/ designated lifting areas for drop weights (funded w/ SPLOST 6)	Inside main building: Rubber floor, not drop rated Field house: Ecore Beast drop rated flooring throughout space (funded w/ SPLOST 6)	Roppe brand, 8mm	Ecore drop rated sports flooring (funded w/ SPLOST 6)
	Functionality	Fair to poor	Good	Good	Good	Good
	Safety	Floor has several bubbles into that could lead to trips and falls	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	Good	Good	Good	Good	Good
	Other	School indicates the floor is inadequate due to multiple area of bubbling and areas that are missing the rubber (separated?) Is the school dropping weights on the floor? If so, is the floor drop rated (need to confirm)	None	None	Floor not rated for dropping weights	None
	Comments	Additional research required regarding flooring	None	Consider installing drop rated flooring in main bldg	Upgrade flooring to drop rated type	None
	Considerations	None	None	Provide new flooring (in main bldg.)	Install drop rated flooring in weight room	None

Paulding County Schools - Athletic, PE Facilities Review

Weight Room		EPHS	HHS	NPHS	PCHS	SPHS
Equipment	Condition	Good	Good	Good	Fair	Good
	Equity	None	Legend equipment; 16 lifting stations (funded w/ SPLOST 6)	Field house equipment: Legend equipment; 9 stations (funded w/ SPLOST 6)	None	Ecore equipment; 8 stations (funded w/ SPLOST 6)
	Functionality	Good	Good	Good	None	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	N/A	N/A	N/A	None	N/A
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None
HVAC	Condition	Good	Good	Good	Good	Good
	Equity	Room conditioned with heating and air	Room conditioned with heating and air	Room conditioned with heating and air	Room conditioned with heating and air	Room conditioned with heating and air
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	N/A	N/A	N/A	None	N/A
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None
Other	Condition	None	None	None	None	Renovated to include new ceiling, Ecore drop rated flooring, weight lighting equipment, LED lights, and wall covering with SPLOST 6 funds
	Equity	None	None	None	None	None
	Functionality	None	None	None	None	None
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	None	None	None	None	None
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None

Paulding County Schools - Athletic, PE Facilities Review

Weight Room		EPHS	HHS	NPHS	PCHS	SPHS
Restroom	Condition	Good	None	None	Good	Good
	Equity	None	None	None	Uni-sex restrooms	Students use PE/Athletic locker rooms and restrooms
	Functionality	Good	No restrooms in space; Students dress out and use restrooms in separate main gym building	None	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	Good	None	None	Good	Good
	Other	None	None	None	None	None
	Comments	Provide management solution for restrooms	Provide management solution for restrooms	Provide management solution for restrooms	Provide management solution for restrooms	Provide management solution for restrooms
	Considerations	None	None	None	None	None

Paulding County Schools - Athletic, PE Facilities Review

Wrestling Room		EPHS	HHS	NPHS	PCHS	SPHS
Room Size	Condition	Good	Do not have one. Wrestling was previously held in fieldhouse football dressing room then moved to a school classroom. Wrestling will now be relocated to the City of Hiram to provide enough room for the program.	Good	Good; room converted from Ag. Sci. to wrestling	Good
	Equity	Size: 2,124 sq ft	None	Size: 1,806 sq ft	None	Size: 1,795 sq ft
	Functionality	Good	None	Fair, Mat takes up entire space	None	Fair, Mat takes up entire space
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	Good	None	Good	None	Good
	Other	None	None	None	None	None
	Comments	None	Field House can be utilized as on-site location	None	None	None
Location	Considerations	None	None	None	None	None
	Condition	None	None	Good	Inside main building, old Ag. Sci. Lab	Good
	Equity	Designated space in main gym	None	Inside main building across from main gym area	None	Inside main building across from main gym area
	Functionality	None	None	Good	None	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	Good	None	Good	None	Good
	Other	None	None	None	None	None
Flooring	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None
	Condition	Good	None	Good	None	Good
	Equity	Wrestling mat material	None	Regular wrestling mat	Wrestling mat used for flooring	Regular wrestling mat
	Functionality	Good	None	None	None	None
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	N/A	None	None	None	None
Other	Other	None	None	None	Mat completely fills the space	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None

Paulding County Schools - Athletic, PE Facilities Review

Wrestling Room		EPHS	HHS	NPHS	PCHS	SPHS
Equipment	Condition	Good	None	None	Good; room converted from Ag. Sci. to wrestling	None
	Equity	None	None	None	None	None
	Functionality	None	None	None	None	None
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	None	None	None	None	None
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None
HVAC	Condition	None	None	Good	Good	Good
	Equity	Room conditioned with heating and air	None	Room conditioned with heating and air	Room conditioned with heating and air	Room conditioned with heating and air
	Functionality	None	None	None	None	None
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	None	None	None	None	None
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None
Other	Condition	None	None	None	None	None
	Equity	None	None	None	None	None
	Functionality	None	None	None	None	None
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	None	None	None	None	None
	Other	None	None	None	No lockers or changing spaces; One single stall restroom in adjoining space	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None

Paulding County Schools - Athletic, PE Facilities Review

Main Gym		EPHS	HHS	NPHS	PCHS	SPHS
Seating	Condition	Good	Good	Good	Good	Good
	Equity	Seating capacity: 1,456	Seating capacity: 1,640	Seating capacity: 1,530	Seating capacity: 1,446 (seat width 18")	Seating capacity: 1,530
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	Good	Good	Good	Good	Good
	Other	None	None	None	None	Movable bleachers malfunction, need repair
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	Repair bleachers
Flooring	Condition	Good	Good; refinished in 2022 Ren/Mod	Fair	Good	Fair
	Equity	Hardwood	Hardwood	Hardwood	Hardwood	Hardwood
	Functionality	Good	Good, refinished in 2022 Ren/Mod	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	Good	Good	Good	Good	Good
	Other	None	None	School indicates there are several areas of concern including rotten spots and "dead" spots	None	None
	Comments	None	None	Repair flooring where needed	None	None
	Considerations	None	None	Repair flooring where needed	None	Re-finish gym floor
Lighting	Condition	Good	Good	Good	Good	Good
	Equity	LED	LED	Fluorescent	Fluorescent	Fluorescent
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	N/A	N/A	N/A	Good	N/A
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None

Paulding County Schools - Athletic, PE Facilities Review

Main Gym		EPHS	HHS	NPHS	PCHS	SPHS
Sound	Condition	Good	Good	Good	Poor, confirm ?	Good
	Equity	None	None	None	None	None
	Functionality	None	None	None	None	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	None	None	None	None	N/A
	Other	None	None	None	None	None
	Comments	None	None	None	Consider repair/upgrading sound	None
	Considerations	None	None	None	Repair or upgrade Sound System	None
Equipment	Condition	Good	Good	Good	None	Good
	Equity	None	None	None	None	None
	Functionality	None	None	None	None	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	None	None	None	None	N/A
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None
Scoreboard	Condition	Good	Good; installed 2022	Fair	Good ?	Fair
	Equity	Brand: Electromech	Brand: Scoretime	None	Brand: ?	None
	Functionality	Good	Good	School indicates there are constant issues with functionality due to maintenance needs on the units	None	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	N/A	N/A	N/A	None	N/A
	Other	None	None	None	None	None
	Comments	None	None	Replace scoreboard	None	Replace scoreboard
	Considerations	None	None	Replace scoreboard	None	Replace scoreboard

Paulding County Schools - Athletic, PE Facilities Review

Main Gym		EPHS	HHS	NPHS	PCHS	SPHS
HVAC	Condition	Good (school indicates inadequate however, HVAC units were replaced in 2018 Ren/Mod	Good	Good	Good	Good
	Equity	Room conditioned with heating and air	Room conditioned with heating and air	Room conditioned with heating and air	Room conditioned with heating and air	Room conditioned with heating and air
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	N/A	N/A	N/A	N/A	N/A
	Other	None	None	None	None	None
	Comments	Good	None	None	None	None
	Considerations	None	None	None	None	None
Locker Rooms	Condition	Good	Good	Good	Good	Good
	Equity	Boys and Girls locker room spaces, 2 Boys and 2 Girls	Boys and Girls locker room spaces, 2 Boys and 2 Girls	Boys and Girls locker room spaces, 2 Boys and 2 Girls	Boys and Girls locker room spaces, 2 Boys and 2 Girls	Boys and Girls locker room spaces, 2 Boys and 2 Girls
	Functionality	None	Good	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	Good	None	None	None	None
	Accessibility	None	Good	Good	Good	Good
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None

Paulding County Schools - Athletic, PE Facilities Review

Aux Gym		EPHS	HHS	NPHS	PCHS	SPHS
Seating	Condition	Good	Good	Good	Fair	Good
	Equity	Seating capacity: 152	Seating capacity: 180	Seating capacity: 228	Has seating on both sides of gym. Aux gym was once used as main competition gym so it has more seating than other schools	Seating capacity: 228
	Functionality	School indicates middle section is unusable due to score board wiring configuration; Maintenance has denied multiple work orders to relocate due to infrastructure and funding concerns	Good	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	Good	Good	Good	Good	Good
	Other	None	None	None	None	None
	Comments	Requires further review	None	None	None	None
	Considerations	None	None	None	None	None
Flooring	Condition	Good	Good; refinished in 2022 Ren/Mod	Fair (confirm?)	Fair	Fair
	Equity	Hardwood	Hardwood	Hardwood	Parquet flooring (only remaining parquet floor in district)	Hardwood
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	N/A	N/A	N/A	N/A	N/A
	Other	None	None	School indicates there are several areas of concern including rotten spots and "dead" spots	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	Repair floor	Re-finish or replace flooring	Re-finish gym floor
Lighting	Condition	Good	Good	Good	Good	Good
	Equity	LED	None	Fluorescent ?	2x4 fluorescent lay in lighting	Fluorescent
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	N/A	N/A	N/A	N/A	N/A
	Other	None	None	None	Acoustical ceiling in poor condition	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	Replace ceiling tile	None

Paulding County Schools - Athletic, PE Facilities Review

Aux Gym		EPHS	HHS	NPHS	PCHS	SPHS
Sound	Condition	None	None	Fair to poor	None	None
	Equity	None	None	None	None	None
	Functionality	None	None	School indicates sound "not good"	None	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	None	None	None	None	None
	Other	None	None	None	None	None
	Comments	District standards do not provide for sound systems in Aux. Gyms	None	District standards do not provide for sound systems in Aux. Gyms	None	None
	Considerations	None	None	None	None	None
Equipment	Condition	None	None	Fair to poor	None	None
	Equity	None	None	None	None	None
	Functionality	None	None	School indicates goal controllers not functioning properly	None	None
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	None	None	None	None	None
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None
Scoreboard	Condition	Good	None	None	None	None
	Equity	Brand: Electromech	None	None	None	None
	Functionality	Good	None	None	None	None
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	N/A	None	None	None	None
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None

Paulding County Schools - Athletic, PE Facilities Review

Aux Gym		EPHS	HHS	NPHS	PCHS	SPHS
HVAC	Condition	Good	Good	Good	Good	Good
	Equity	Room conditioned with heat and air	Room conditioned with heat and air	Room conditioned with heat and air	Room conditioned with heating and air	Room conditioned with heat and air
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	N/A	N/A	N/A	N/A	N/A
	Other	None	None	None	None	School indicates possible leak in HVAC
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None

Paulding County Schools - Athletic, PE Facilities Review

Locker Rooms		EPHS	HHS	NPHS	PCHS	SPHS
PE Lockers	Condition	Good	Good	Good	Good	Good
	Equity	Locker count: boys, 144; girls, 132	2 Boys and 2 Girls	Locker count: boys, 558; girls, 558	2 Boys and 2 Girls	Locker count: boys, 558; girls, 558
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	Good	Good	Good	Good	Good
	Other	School indicates HVAC needs to be installed for all locker room areas	No designated boys athletic locker room space. Locker room is there, it just isn't outfitted like the girls athletic. Girls space is very small and compact. Needs correct signage	None	Was once the main competition gym, so space has both athletic and PE spaces. Total locker room count between both Aux Gym (former Comp. Gym) and Main Gym: 4 Boys and 4 Girls	None
	Comments	None	School to provide management solution for boys athletic locker room	None	None	None
	Considerations	None	Install correct signage	None	None	None
Boys Restroom	Condition	Good	Good	Good	Good	Good
	Equity	Fixture count: PE: 3 stalls, 2 showers; Athletics: 3 stalls, 2 showers; all boy locker rooms have designated restrooms	All boy locker rooms have designated restrooms	Fixture count: PE: 5 stalls, 4 showers; Athletics: 6 stalls, 4 showers; all boy locker rooms have designated restrooms located in space	All Boy locker rooms have designated restrooms located in the space	Fixture count: PE: 5 stalls, 4 showers; Athletics: 6 stalls, 4 showers; all boy locker rooms have designated restrooms located in space
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	Good	Good	Good	Good	Good
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None
Boys Dressing Room	Condition	Good	Good	Good	Good	Good
	Equity	Space for dressing in all boy locker rooms	Space for dressing in all boy locker rooms; no lockers in boys athletic space	Athletic locker count: 46; space for dressing in all boy locker rooms	Space for dressing in all Boy locker room spaces	Athletic locker count: 46; space for dressing in all boy locker rooms
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	See previous note concerning athletic locker space	None	None	None
	Accessibility	Good	Good	Good	Good	Good
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None

Paulding County Schools - Athletic, PE Facilities Review

Locker Rooms		EPHS	HHS	NPHS	PCHS	SPHS
Boys Showers	Condition	Good	None	Good	Good	Good
	Equity	PE: 2 showers; Athletic: 2 showers	None	PE: 4 showers; Athletic: 4 showers	In Aux Gym, Open bay pedestal style showers; In Main Gym, individual stall showers	PE: 4 showers; Athletic: 4 showers
	Functionality	Good	None	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	Good	None	Good	Good	Good
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None
Girls Restrooms	Condition	Good	Good	Good	Good	Good
	Equity	Fixture count: PE 4 stalls, 2 showers; Athletics: 4 stalls, 2 showers; all girl locker rooms have designated restrooms	all girl locker rooms have designated restrooms	Fixture count: PE 5 stalls, 4 showers; Athletics: 6 stalls, 4 showers; all girl locker rooms have designated restrooms located in space	All Girl locker rooms have designated restrooms located in the space	Fixture count: PE 5 stalls, 4 showers; Athletics: 6 stalls, 4 showers; all girl locker rooms have designated restrooms located in space
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	Good	Good	Good	Good	Good
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None
Girls Dressing Rooms	Condition	Good	Good	Good	Good	Good
	Equity	Space for dressing in all girl locker room spaces	Space for dressing in all girl locker room spaces	Athletic locker count: 46; space for dressing in all girl locker room spaces	Space for dressing in all Girl locker room spaces	Athletic locker count: 46; space for dressing in all girl locker room spaces
	Functionality	Good	Good	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	Good	Good	Good	Good	Good
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None

Paulding County Schools - Athletic, PE Facilities Review

Locker Rooms		EPHS	HHS	NPHS	PCHS	SPHS
Girls Showers	Condition	Good	None	Good	Good	Good
	Equity	PE: 2 showers; Athletic: 2 showers	None	PE: 6 showers; Athletic: 4 showers	In Aux Gym, individual stall showers; In Main Gym, individual stall showers	PE: 6 showers; Athletic: 4 showers
	Functionality	Good	None	Good	Good	Good
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	Good	None	Good	Good	Good
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
Team Locker Rooms	Considerations	None	None	None	None	None
	Condition	None	None	None	None	None
	Equity	None	None	None	None	None
	Functionality	None	None	None	None	None
	Safety	None	None	None	None	None
	Title IX	None	None	None	None	None
	Accessibility	None	None	None	None	None
	Other	None	None	None	None	None
	Comments	None	None	None	None	None
	Considerations	None	None	None	None	None